New Applications for W/E 20-11-26

26/01732 HAMILTON COURT, EASTWICK PARK AVENUE

BOOKHAM KT233LR(06/01) Link

Reference TPO/107/2/N T7, Sycamore, fell. T11, Sycamore, Crown lift to 4 meters over car park. T12, Sycamore, Prune clear of building by 1.5 meters. T20, Sycamore, Prune clear of building by 2 meters. T21, Sycamore, Reduce crown height by 2.5m. Reduce crown spread by 1.5-2m. Install non invasive cable brace in upper one third of the crown to support weak union. Finished height to be 15m with an average radial spread of 7m. T22, Sycamore, Sever Ivy at ground level and remove 1.5m of Ivy from the stem. Reduce crown height by 5m. Reduce crown spread by 3m to the North. Finished height to be 12m with an average radial spread to the North of 5m. T27, Hawthorne, Sever Ivy at ground level and remove 1.5m of Ivy from the stem. Crown lift to 2.5m over the footpath. Reduce crown spread by 1m to the West. T34, Ash, fell. ADB present. T36, Sycamore, Remove severely damaged crossing branch at 5m. T37, Larch, Dead, fell. T40, Larch, Sever Ivy at ground level and remove 1.5m of Ivy from the stem. Reduce crown height by 3.5m. Reduce crown spread by 4.5m to the North. Finished height to be 10m with a radial spread to the North of 9m. T41, Ash, Sever Ivy at ground level and remove 1.5m of Ivy from the stem. Reduce the extended lateral limb to the South growing towards the footpath by 2.5m. Finished Radial spread of limb to be 5.5m. Monitor in the future. T44, Larch, dead, fell. T45, Sycamore, Sever Ivy at ground level and remove 1.5m of Ivy from the stem. Reduce crown height by 6m. Reduce crown spread by 2m. Finished height to be 12m with an average radial spread of 4.5m. T46, Sycamore, Sever Ivy at ground level and remove 1.5m of Ivy from the stem. Reduce crown spread by 2.5m to the South. Selectively remove or reduce badly squirrel-damaged branches. Finished radial spread to the South to be 5m. T47, Sycamore, Sever Ivy at ground level and remove 1.5m of Ivy from the stem. Reduce crown spread by 2m. to the South. Selectively remove or reduce badly squirrel damaged branches. T49 and 51, Elm, dead, fell. G52, Group Elm, dead, fell.**Case Officer:** Lee Harper

26/01751 55 EASTWICK DRIVE BOOKHAM KT23 3PU (14/12) Link

Demolition of existing dwelling and erection of 3 No. dwellings with associated amenity and parking with access from Eastwick Drive. **Case Officer:** Sue James

26/01714 THE COTTAGE FOXMEAD MADDOX LANE BOOKHAM KT23 3BS (11/12) Link

Erection of a detached outbuilding. **Case Officer:** James Halls

26/01721 29 CHURCH ROAD BOOKHAM KT23 3PG (11/12) Link

Erection of 1 No. non-illuminated fascia sign and 1 No. non-illuminated projecting sign.

Case Officer: Sophie Day

26/01741 2 WEST DOWN BOOKHAM KT23 4LJ (13/12) Link

Demolition of existing conservatory and front porch and erection of a two-storey side extension and front porch with pitch roof to single storey front element, replacement windows, change of external finish to render with timber cladding and erection of a 1.8 metre high close boarded fence to replace existing hedge.**Case Officer:** James Halls

26/01744 9 FIONA CLOSE BOOKHAM KT23 3JU (13/12) Link

Demolition of rear conservatory and side extensions including garage and the erection of single storey extensions to front, side and rear. **Case Officer:** Sophie Day

26/01746 BEEHIVE FARM MADDOX LANE BOOKHAM KT23 3HT (24/12) Link

Submission of details pursuant to Conditions 3 (External Surface Materials) and 11 (Carbon Emissions) of planning permission 23/1098 for the erection of replacement dwelling following demolition of existing bungalow.**Case Officer:** Chris Yeoell

(*) Denotes Response Deadline date or Expiry date when shown in red.