

New Applications for W/E 15-05-26

26/00565 34 GILMAIS BOOKHAM KT23 4RP

(04/06)

[Link](#)

TPO/107/3/J- Walnut Tree (T1) - cut back overhang to old reduction points (up to 2m), thin remainder of tree by 20% and remove major dead wood to create more light.

26/00572 10 FARM CLOSE FETCHAM KT22 9BJ

(05/06)

[Link](#)

Replacement of flat roof to detached garage with a pitched roof.

26/00594 OAK DEAN MEADOWSIDE BOOKHAM KT23 3LF

(07/06)

[Link](#)

Erection of single storey side extension with 3 No. roof lights to side roof slope; relocation of detached double garage to front of property and alteration to existing front dormer window.

26/00605 48 KESWICK ROAD BOOKHAM KT23 4BH

(08/06)

[Link](#)

Demolition of detached garage and timber shed and single storey rear element and erection of part single, part two storey side and rear extension.

26/00570 GREY GABLES, TUDOR CLOSE BOOKHAM KT23 3DP

(05/06)

[Link](#)

Demolition of single-story side element and erection of a single storey rear extension, two storey side extension, first floor front extension, 1 No. dormer window to rear and 1 No. rooflight to both sides and front to create rooms in roof space.

26/00574 6 VICARAGE CLOSE BOOKHAM KT23 3DZ

(05/06)

[Link](#)

Erection of single-storey porch enclosure and new first floor pitched roof dormer to the front, two rooflights to the rear and fenestration alterations.

26/00580 6 VICARAGE CLOSE BOOKHAM KT23 3DZ

(25/05)

[Link](#)

Certificate of Lawfulness for a proposed development in respect of a rear flat roof dormer window.

26/00587 28 NEWENHAM ROAD BOOKHAM KT23 4NJ

(12/06)

[Link](#)

TPO/107/3/F. Felling of beech tree to ground level -The tree has visible Ganoderma fungal brackets at the base, indicating significant decay and potential structural weakness. This presents a risk of failure and potential harm to nearby property and persons. Removal is proposed on safety grounds.

26/00589 28 NEWENHAM ROAD BOOKHAM KT23 4NJ

(12/06)

[Link](#)

TPO/107/3/F. European Beech (*Fagus sylvatica*) Felling of beech tree to ground level. As the tree has visible Ganoderma fungal brackets at the base, indicating significant decay and potential structural weakness. This presents a risk of failure and potential harm to nearby property and persons. Removal is proposed on safety grounds.

26/00591 HORSE CHESTNUT COTTAGE POST HOUSE LANE BOOKHAM KT23 3EA (07/06) [Link](#)

Erection of single storey rear extension, alteration to boundary to incorporate land within the adjoining property of Cedar Cottage and erection of tool shed in extended garden area.

(*) Denotes Response Deadline date or Expiry date **when shown in red.**